

Model:
TPE331-10U- 502G
SN: P-35115



December 08, 2006

TSN: 1257.8
CSN: 1870

TURBINE STANDARD, LTD.
1640 COMMERCE RD. · HOLLAND, OH · 43528
BUS: (419) 865-0355 · FAX: (419) 865-2460
FAA CRS: X2ZR927X

Disassembled engine and inspected for repair and service bulletin update. Accessory Drive Housing repaired due to corrosion and modified to PN 3107114-3 SN 9-08169-1048 due to severe corrosion. Engine boxed for shipment in **Disassembled UN-AIRWORTHY** condition per customer request. Further Inspections, Repair and Testing required in accordance with applicable Maintenance Manuals prior to return to service. Pertinent details of all work completed on file at Turbine Standard, Ltd. Under Work Order:80582.

David R. Corwin *for* FAA CRS:X2ZR927X

Form: TSL10070A