



Turbine Standard, Ltd.

10550 Industrial Rd.
Holland, OH 43528
TEL: (419) 865-0355 FAX: (419) 865-2460
FAA CRS: X2ZR927X



ENGINE MODEL: TPE331-10U-512G

ENGINE SN : P-35117C

DATE : April 13, 2011

TSN : 1306.6

CSN : 1905

Completed **Limited Repair, Level II Prop Strike Inspection, 3700 Hour FCU/ Fuel Pump Integrity Inspection and the Annual Magnesium Housing Corrosion Inspection** in accordance with Maintenance Manual Report 72-00-23, R14 and SB 72-0180, R31 7000 Hour TBO Program. Major Parts installed include but are not limited to: **New:** Compressor Bearing PN: 3101405-1, SN: 10-151725-06045. Test Run Completed. Re-Compensation, Torque System Calibration, Vibe Survey and all required Functional/Leak Checks carried out. **New DSC and Torque Data issued.** For pertinent details of all work completed on file at **Turbine Standard, Ltd.** under Work Order 81981.

*******END*******

****NOTE****

THIS ENGINE IS CONFIGURED FOR OPERATION IN ACCORDANCE WITH 7000 TBO PROGRAM AS SPECIFIED IN HONEYWELL SERVICE BULLETIN TPE331-72-0180, Rev 31.

SEE CHAPTER 72-00-00 OF MAINTENANCE MANUAL 72-00-23 FOR REQUIRED SYSTEM CHECKS AT ENGINE INSTALLATION

S.O.A.P. SAMPLES REQUIRED WITHIN 5 – 10 OPERATING HOURS AND AGAIN AT 20 – 30 OPERATING HOURS FOLLOWING THIS INSPECTION

Signature :

Dan M. Dunn for FAA CRS: X2ZR927X

Turbine Standard, Ltd.

10550 Industrial Rd.– Holland, OH - 43528

FORM: TSL10070B